Guidelines for visitors and lorry drivers



- You enter and/or drive on the works premises on your own responsibility! Only enter the building that you are registered for and report directly to your contact person. Entry to the production area is only permitted when accompanied by martinswerk staff!
- Smoking is prohibited in specially indicated areas!

operating instructions, e.g. at loading bays.



■ In the buildings and on the roads and areas of the production, storage and loading areas, **Safety helmets**, safety goggles and safety shoes must be worn S3. Ear protection must be worn in the areas indicated. Drivers and assistants that carry out loading tasks must also wear safety jackets and protective clothing. Conditionally observe the information given in











- Drivers delivering or loading hazardous materials (e.g. leachate, acids) must adhere to the corresponding special safety measures!
- **Private passengers** must not leave the lorry cab except in the area of the factory entrance. Animals must always remain in the lorry cab.



- Accidents, fire and other emergencies must be reported via our internal Emergency number 777. Our emergency reporting and first-aid centre is at the main reception!
- Photography is forbidden within the complete works premises!



■ The use of electronic devices (headphones, mobile etc.) is forbidden in the potentially explosive areas!



For driving within the works premises: Attention for pedestrians, cyclists and works traffic! The road traffic regulations are applicable throughout the works premises. The maximum speed within the works premises is 20 km/h, in the area of the weighbridge 10 km/h. Railed vehicles have priority. Attention at pedestrian and rail crossings! Give priority!







- When the vehicle is stationary, the engine must be switched off!
- Entry permits and all loading papers must be produced unsolicited to the porter when leaving!
- Adhere to the instructions of the porter!
- Right of dwelling will expire by infringement or disregard and banning from the works must also be expected!



